

### Laboratory of Places 2018

**Presentation Group 2** 

Summer School: Surveying Cultural Heritage

7th Edition
July 23 to August 1, 2018










#### Chapel number III: «First fall of Jesus»






The chapel was built in 1908 and it is located in the valley of Domodossola Calvario. It is the last to be built.

## Photogrammetry

#### **STEP 1: Taking Photos**

#### DSC 1999/ DSC 19


Main Facade



Side one Facade

# Doc 1990 Doc 19

**Back Facade** 



Side two Facade

#### Main issues

- Location
- Setting camera
- Camera position
- Loss of markers

#### **Solution**

- Preparation
- Organization
- Check during phase
- Aboundance of markers

#### **STEP 2: Drone Photos**









#### **STEP 3: Orthophotos**



**Main Facade** 




Side one Facade

- One camera
- Software
- Accuracy
- High resolution
- Cheap

## Topography

#### **Useful to:**



- Correct disposition in the space
- Scale the model
- Link data information




### Laser Scanner

#### **STEP 1: Target position and station definition**


#### **Main issues**

- Weather condition
- Assign markers






#### **STEP 2: Products**



#### Problem 1

#### **Main issues**

- Double line
- Cloud alignment
- Loss of markers
- Location



#### Problem 2

#### **Main issues**

- Supporting information
- Complex geometry
- Rapid survey






## Material and Decay mapping

#### Method

#### Conservation






## 3D mobile







Emb3D

